
Replacement Sheet

1/4



Shallow Trench Isolation Process Flow

- 1. Pad Oxide
- 2. Nitride: Trench Etch Hard Mask and CMP Stop Layer
- 3. Island Mask
- 4. Trench Etch
- 5. Oxide Liner: Corner Rounding
- 6. Trench Fill
- 7. Densification (Can Be Skipped)







FIG._1
(PRIOR ART)

Replacement Sheet

2/4



+